

REPORT



STRUCTURE PAINTING CONDITION AT SPM

Report No	QR_10
Made by	Luu Thanh Lam
Date	12 th - Sep-2023

SURROUNDING STRUCTURE



























TOP STRUCTURE



TOP STRUCTURE



Floating hoses

SECTION- NO.1





01



02



03



04



05



06

07

08

10



11

12

09












SECTION- NO.2







29



30








31



32











45



SECTION- NO.3





48

49

51


53

54

55

50

52



56



57



58



59



60






61


62

63

64



SECTION- NO.4





69

70

71

72



73




74



75





76

77




78

79



OTHER STRUCTURE



83

82

81

80



83




82



81



80



86

85

84



87

88










91

92

93

94







END